

NEIL F. HARTIGAN ATTORNEY GENERAL STATE OF ILLINOIS SPRINGFIELD

July 30, 1985

Mr. Kevin Phillips Ecology and Environment, Inc. 111 West Jackson Blvd. Chicago, Illinois 60604

Dear Kevin:

Enclosed is the water analysis results from the water analysis results from the water analysis well in Rock Falls. Please let me know if your chemists are able to make anything of this information.

As you may already know, there is an auto paint shop, a bulk oil storage plant and an asphalt storage plant all within a block of the Notesponsive home. At one time there were at least two other bulk oil facilities and a cement plant located nearby. These have since been dismantled.

Notresponsive was able to determine the owner and use of the building you mentioned in our recent conversation. Apparently it was used as a bulk storage facility of some sort. Unfortunately, I have not been able to speak to her personally regarding this, as yet.

Of course, you know that Masonite/Roxite is located about 1/3 of a mile from the Notresponsive home. They manufacture reinforced fiber-glass building products.

I will keep you informed of further developments. I would appreciate your doing the same for me. Thank you.

Sincerely,

Michael L. Risse

Hazardous Waste Investigator

Rock Island Regional Office 310 - 20th Street Rock Island, Illinois 61201

MLR/pv Enclosure

EPA Region 5 Records Ctr.



936848